




**ASSISTANT RESIDENT ENGINEER'S DAILY INSPECTION REPORT:**

**PHOTOS**



Intersection: prohibit right turn into construction work zone eastbound



Traffic control for K rail placement



West Broadway closure at Del Monte Ave

**Kathryn Lett**

**Inspector**