



West Broadway Urban Village
 Infrastructure Improvements Project
 City of Seaside
 Project No. 2016-76
 Federal No. ATPL-5316 (007)

Report No: **43**
 Date: **08/04/17**
 Day: **Friday**
 Shift Hours: Start **0700**
 Stop **1500**

- | | | |
|---|--|--|
| <input type="checkbox"/> Material Source Inspection | <input type="checkbox"/> Certificate Of Compliance | <input type="checkbox"/> Employee Interview |
| <input type="checkbox"/> Material Inspected and Released on Job | <input type="checkbox"/> Acceptance Test (IA) | <input type="checkbox"/> Photos |
| <input checked="" type="checkbox"/> No Quality Documents Required | <input type="checkbox"/> Quality Documents Submitted | <input type="checkbox"/> Tentative Agreement |

ASSISTANT RESIDENT ENGINEER'S DAILY INSPECTION REPORT Page 1 of 1

HOURS - ITEM No. or CCO No.

M = Monterey Peninsula Engineering
 SA = Stripe Alot
 CC = Central Coast Surveyors
 DJ Kirkpatrick Sawcutting = KS
 Penhall = P

WEATHER
 AM 60°F +/-
 PM 84°F +/-
 Clear

PRECIP
 wind: 0-10 mph

| Con | NO. | EQUIPMENT / MAKE | 8 | 100 | 55 | 56 | LABOR - TRADE / NAME |
|-----|-----|--------------------------|---|-----|----|----|----------------------------------|
| M | | Backhoe, Case 590 | | | | 5 | 3 Bulmaro-Reyes, Chino; operator |
| M | | Water Truck, 2200 gallon | | | 8 | | Reyes, Ron; laborer |
| M | | Pick Up | 1 | | 7 | | Sandoval, Manual J; laborer |
| M | | Vibratory Plate, Mikasa | | | | 3 | 5 Bulmaro-Reyes, Chino; operator |
| M | | Excavator, Deere 225D | | | 6 | 2 | Honeycut, Ritchie; foreman |
| M | | Excavator, Deere 225C | | | | 8 | |
| M | | Excavator, Kobelco SK220 | | | | 8 | |
| M | | Gradall, Sky Trak | | | | 8 | |
| M | | Dump Truck, two axle | | | | 8 | |
| M | | Fork Lift | | | | 8 | |
| M | | Grader, Cat 140H | | | | 8 | |
| M | | Bobcat 963 | | | | 8 | |

MPE continued construction of Drainage Structure 3. DS 5 concerns and changes were discussed with the MPE foreman.
 Dust control by watering exposed areas. All traffic control devices and configurations operational.

Today's Qtys (approx.)

Kathryn Lett, Asst Res Engineer
 Inspector